



LEGEND

- Set 1/2" Rebar W/ CAP L.S. 31020 (unless otherwise noted)
- Property Line
- Fnd Survey Monument (See Monument Table)
- ① (See Monument Table)
- (R) See Reference Documents
- (M) Measured

MONUMENT TABLE	
①	SE. COR. SEC. 30 - FND G.L.O. BRASS CAP
②	S. 1/4 COR. SEC. 30 - FND MARICOPA COUNTY ALUMINUM CAP
③	CEN. OF SEC. 30 - FND 1" IRON PIPE W/TAG L.S. 6177 AS SHOWN ON (R2)
④	E. 1/4 COR. SEC. 30 - FND MARICOPA COUNTY ALUMINUM CAP L.S. 36563
⑤	SW. COR., NW. 1/4, SE. 1/4, SEC. 30 - FND 1/2" REBAR W/CAP L.S. 31020 PER (R2) - ALSO FND 1/2" REBAR W/NO I.D. S. 28°37' E. 0.91' AS SHOWN ON (R2)
⑥	SE. COR., NW. 1/4, SE. 1/4, SEC. 30 - FND 1/2" REBAR W/CAP L.S. 31020 PER (R2)
⑦	NE. COR., S. 1/2, NW. 1/4, SE. 1/4, SEC. 30 - FND 1/2" REBAR W/CAP L.S. 31020 PER (R3)
⑧	FND 1/2" REBAR W/CAP L.S. 31020 PER (R3)
⑨	FND 1/2" REBAR W/CAP L.S. 31020 PER (R2)
⑩	FND 1/2" REBAR W/CAP L.S. 38863

LINE	BEARING	DISTANCE
L1	S 89°59'14" E	31.91'
L2 (R2,M)	S 89°59'14" W	55.00'
L3	N 89°59'14" W	20.00'

**-PRELIMINARY-
NOT FOR
CONSTRUCTION
OR RECORDING**

**-PRELIMINARY-
NOT FOR
CONSTRUCTION
OR RECORDING**

LAND DIVISION SURVEY

ALLIANCE
LAND SURVEYING, LLC
7800 N. 70th AVENUE, SUITE 104 Phone: (623) 972-2200
GLENDALE, AZ 85303 contactus@alliance.com
www.alliancelandsurveying.com